

ABSTRACT

A method for granulating a flexible polyolefin resin including steps of melting a flexible polyolefin resin, and
5 melt-kneading the resin while cooling the resin to a temperature of the melting point (T_m-D) of the resin or less.